Gantry Alignment macro wizard helps to generate macro for dual motor gantry alignment. There can be several methods for gantry alignment. Almost any of method can be implemented by (advanced) user through macro/PLC layer. We can offer 2 methods for gantry alignment.

Method 1

2 sensors on each side of gantry used to find side position. The alignment procedure is described below-

1. CNC activates motors on both sides and moves toward the sensors.



2. When one of the sensors is triggered, CNC control disconnects motor on this side, the 2nd motor continues to move.





- 4. In case of sensors, the position should be adjusted at this point can be setup move of 1 motor to given adjustment distance.
- 5. Both motors are activated and move together.

Motor1	Motor2

6. The machine moves out from the sensors for given distance. \blacksquare

To generate this kind of alignment macro can be used the wizard. See below a screenshot of the Gantry Alignment Wizard

SYS CFG									r be
Preferences Profile Macros PLC Builder A	xes/Motors Inputs/Sensors	5 Technology	Network	Camera	5 axes RTCP	Panel/Pendant	Hardware	Advanced	
Macro List Macro Wizard Probing Wizard	Macro List Macro Wizard Probing Wizard								
Homing Homing XY Gantry Alignment Back to Path Surface Measure Tool Length Measure Tool Change									
Axis, Direction Y - Macro preview									
Sensor numbers 0 1 0 Bo	10 L80 P5521 Q1								
Use Encoder Z signals for 0 = 0 Bo	s10 E80 PS525 Q1 481 L3204 P256 391 G0 Y-1000.0000 F 500.00								
Ignore Limits while align 🔽	04 P0.1 91 G0 Y 10.0000 79 J 3204 P0	F 500.00							
Align while move: Forward -	G	91 G0 Y 2.3500 79 3204 P1	F 500.00						
Final tuning (Motor#1 2.35	G	G90 G10L70 P0 Y #5452 G10 L80 P5521 Q0							
Double check	0	10 280 -3525 Q0							
Move distance 1000	•								
Gap 10									
Speed / Slow Speed 500	50								
Position After Align **(Set the Value in Homing Tab for selected axis)									
Reset work position after align									
Macro header									
Macro footer									
Macro filename 🔹									
Generate :	Save macro								

On the screen we have

- 1. Axis, Direction Macro is generated for Y axis
- 2. While alignment machine moves toward Y-MIN
- 3. **Sensor numbers** sensor #0, #1 are used as sensors on each side of gantry, both senors are "Normally Closed"
- 4. Use Encoder Z signals for align not used
- 5. Ignore Limits while align If sensors #0 or #1 is used as limit sensor, then Limits should be

ignored (put check-box) while alignment to prevent abort procedure.

- 6. Align while move Forward
- 7. Final tuning (Motor #1 offset) set distance to adjust sensors
- 8. Double check (to be described later)
- 9. **Move distance** Distance expected from start position to alignment sensors. This distance should be set a more than real distance to alignment sensors.
- 10. **Gap** move out from the sensors for given distance.
- 11. **Speed** speed for motion toward the sensors
- 12. **Slow Speed** not used for "Align while move:Forward" method.
- 13. Reset work position after align
- 14. Macro filename File name to ave macro source to file.

To generate and save macro (As usual for the Macro wizard) 3 buttons should be pressed

- 1. Save (top-right corner to save macro wizard settings and use them for future macro generate
- Generate to generate macro source and show it in "Macro preview" window. If Generate button pressed, new macro is shown ONLY in the preview window and is not activated !! At this point, auser can manually edit the macro source in Macro preview window
- 3. Save Macro save macro from Macro preview for the macro file with the name given in Macro filename, then reload all macros to CNC memory.

Gantry Alignment procedure either can work simultaneously as a homing procedure (if the alignment sensor is used as a homing sensor as well), or Homing procedure can be run just after gantry alignment procedure.

Method 2

2 sensors on each side of gantry used to find each side positions. When both sensors actual positions found, CNC control moves the only side to get the gantry aligned.

The alignment procedure is described below-

1. CNC activates motors on both sides and moves toward the sensors.



2. PLC controoler procedure latches machine positions at the moment every sensor is triggered.



3. Motion stopped at the moment both sensors are triggered.



- 4. PLC procedure calculates the difference between latched positions and add an adjustment offset
- 5. The second motor control temporarily disabled, the first motor only is rotated accordingly calculated adjustment



6. Then the second motor control is activated again and both motors moved together



That's the plan. How to implement it? Here is step-by-step implementation description.

 CNC activates motors on both sides and moves toward the sensors. Actually both motors for the gantry should be configured in "Axes/Motors" configuration widget by default. However, extra M-code can be used to be sure both motors are turned on. For example, M219.plc connects axis X to both motor output #0 and #1

M219.plc

```
#include vars.h
main()
{
 parameter=0+16; //"0" is axis X; "16" is axis inversion.
//parameter=1+16; //"1" is axis Y; "16" is axis inversion.
//parameter=2+16; //"2" is axis Z; "16" is axis inversion.
//parameter=3+16; //"3" is axis A; "16" is axis inversion.
//parameter=4+16; //"4" is axis B; "16" is axis inversion.
//parameter=5+16; //"5" is axis C; "16" is axis inversion.
command=112+0; //Motor output #0
message=PLCCMD SET CNC VAR;
 timer=2;do{timer--;}while(timer>0);
 command=112+1; //Motor output #1
 parameter=0+16; //"0" is axis X; "16" is axis inversion.
message=PLCCMD SET CNC VAR;
 timer=2;do{timer--;}while(timer>0);
exit(99);
};
```

• PLC controller procedure latches machine positions at the moment every sensor is triggered. For this example, we use procedure M144.plc written specially for the example. Any other implementation can be used as well

M144.plc

```
#include pins.h
// Look after INPUT GANTRY S1 & INPUT GANTRY S2 input pins
// Position X is stored in register #801 when sensor s1 triggered
// Position X is stored in register #802 when sensor s2 triggered
// If both sensors triggered, then
// - Motion stopped
// - Position difference is calculated and stored into register #800
main()
 timer=0;
 message=PLCCMD MOTION CONTINUE;
 texit=timer+30; do{timer++; }while(timer<texit);</pre>
 mode 12=0;
 ready=0;
 s1_old=portget(INPUT_GANTRY_S1);
 s2 old=portget(INPUT GANTRY S2);
 do
 Ł
 timer++:
 s1=portget(INPUT GANTRY S1);
 s2=portget(INPUT GANTRY S2);
 mode1=mode_12&1;
 if (model==0)//if sensor 1 wasn't triggered
 {
  if (s1!=s1 old) //if triggered now
   {
     mode 12=mode 12|1; //set flag for sensor1
     position1=gvarget(5021+0); //Save Machine X position
   };
 };
 mode2=mode 12\&2;
```

```
if (mode2==0)//if sensor 2 wasn't triggered
 {
 if (s2!=s2_old) //if triggered now
   {
     mode 12=mode 12|2; //set flag for sensor2
     position2=gvarget(5021+0); //Save Machine X position
  };
};
}while(mode 12!=3);
message=PLCCMD MOTION SKIP;
timer=2;do{timer--;}while(timer>0);
gvarset(801, position1); //send the position to myCNC software Register
#801
timer=50; do{timer--;}while(timer>0);
gvarset(802, position2); //send the position to myCNC software Register
#802
timer=50;do{timer--;}while(timer>0);
 offset=position1-position2;
 gvarset(800, offset);
timer=50;do{timer--;}while(timer>0);
exit(99);
};
```

The M144.plc procedure uses predefined values as the input pin numbers the alignment sensors connected to

```
#include pins.h
...
sl_old=portget(INPUT_GANTRY_S1);
s2_old=portget(INPUT_GANTRY_S2);

do
{
...
s1=portget(INPUT_GANTRY_S1);
s2=portget(INPUT_GANTRY_S2);
...
...
```

Actual input numbers should be defined in define file "pins.h". The content of "pins.h" file should be included at the start of each macro. If using this programming style, the "pins.h" is the single file you need to edit to customize your input/output assignments.

pins.h

```
#define INPUT_GANTRY_S1 3
#define INPUT_GANTRY_S2 4
...
```

You can put numbers directly to portget/portset functions of PLC source (however, we don't recommend this). It will look like this

```
...
s1_old=portget(3);
s2_old=portget(4);

do
{
...
s1=portget(3);
s2=portget(4);
...
```

• Motion stopped at the moment both sensors are triggered. This is implemented in the M144.plc

PLC sends message to the Motion controller to end the current motion and jump to the next g-code line

```
message=PLCCMD_MOTION_SKIP;
timer=2;do{timer--;}while(timer>0);
```

• PLC procedure calculates the difference between latched positions and adds an adjustment offset. This is implemented in M144.plc as well

```
gvarset(801,position1); //send the position #1 to myCNC software Register
#801
timer=50;do{timer--;}while(timer>0);
gvarset(802,position2); //send the position #2 to myCNC software Register
#802
timer=50;do{timer--;}while(timer>0);
offset=position1-position2; //calculate the difference
```

```
gvarset(800,offset); //send the difference to myCNC software Register #800
```

timer=50;do{timer--;}while(timer>0);

• The second motor control temporarily disabled, the first motor only is rotated accordingly calculated adjustment.

Connect/disconnect Axis X from motor output pin is implemented in the M210.plc procedure. Depends on external parameter (which is P-parameter in G-code line), the procedure sends either "15" to disconnect motor output #1 or "16" to assign **Inverted Axis X** to the motor output #1.

M210.plc

```
#include vars.h
main()
Ł
 connect=eparam;
message=PLCCMD_SET_CNC_VAR;
if (connect==0)
 {
  parameter=15; //OFF
}else
 {
  parameter=0+16; //"0" is axis X; "16" is axis inversion.
 };
 command=112+1; //Motor output #1
 timer=2;do{timer--;}while(timer>0);
exit(99);
};
```

As a result,

- Code to disconnect motor output#1 is M210 P0
- Code to connect motor output#1 to axis X is M210 P1
- Then the second motor control is activated again and both motors moved together. G-code G28.9 can be used to move axis accordingly register value.

G28.9 X810 (# Move X coordinate to the position stored in register #810)

A complete macro to gantry alignment (Method #2) is shown below

M139

```
M144 (# Set watching for GANTRY Sensors)
G91 G0 X-1000 F500 (# Move toward Gantry Sensors)
( It takes a time PLC controller from M144 procedure sends )
```

(updated register #800, #801, #802 values to myCNC control software) (Add 0.5 seconds pause to get all the registers updated) G4 P0.5 (# Pause) G10 L81 P810 Q800 (# Get offset in pulses) G10 L192 P810 Q5531 (# Calculate offset in units/mm) G10 L190 P810 Q805 (# Add adjustment offset) M210 P0 (# OFF the second motor, the Only first motor is ON) G10 L190 P810 05021 (# Add current machine position) G28.9 X810 (# Move 1 motor to adjust) M210 P1 (# ON the second motor, both motors are moved together)

Method 2+

What should be changed if Gantry alignment procedure needed for other axis (for example Y axis instead of X)

1) Let's say Motor outputs #0 and #1 configured as Y.

SYS PLC Log Stat Info S	Support Cutchart Cont	fig							<u></u>
CNC Settings	Enabled		Pulses per Unit	Max Speed	Backlash	Axes mapping		Speed profile	
Axes/Motors	x		700	15000	0	x			
> Inputs/Outputs/Sensors	v		700	15000		v			
- Network						·			
Motion	2			6000	<u> </u>	۷			
>- Hardware PLC	A	×	82.3723229	0	0	A1 - rotation around X	\geq	Constant surface speed 🛛 🖂	
- Software PLC	В	X	82.3723229	0	0	B1 - rotation around Y	\sim	Constant surface speed 🛛 🖂	
- DXF import settings	с	×	82.3723229	0	0	C1 - rotation around Z	\geq	Constant surface speed 🛛 🖂	
- Macro List		×		0	0	×		Slave of XYZ	
> - Macro Wizard	v			0	0	×		Slave of XYZ	
> - Probing Wizard	Scan along rotationa	l axis	·						
>- Preferences	Motor outputs confic	urat	ion	-					
> - Screen	Attach To	Axis	Inversion						
- Work Offsets	Motor #0 Y	찐							
 Parking Coordinates 	Motor #1 V								
> - Technology									
– Camera									
- 5 axes RTCP	Motor #3 Z	\geq	×						
> Panel/Pendant	Motor #4 A	\Box	×						
> Hardware	Motor #5 B	찐							
>- Advanced	Motor #6	ᆸ							
			_						
		<u> </u>							
	Servo drivers configu	iratio							
	Servo ON output		Output 48 🖂						

2) Procedure to connect both outputs to Y axis will look as

M219.plc

```
#include vars.h
main()
{
//parameter=0+16; //"0" is axis X; "16" is axis inversion.
 parameter=1+16; //"1" is axis Y; "16" is axis inversion.
//parameter=2+16; //"2" is axis Z; "16" is axis inversion.
//parameter=3+16; //"3" is axis A; "16" is axis inversion.
//parameter=4+16; //"4" is axis B; "16" is axis inversion.
//parameter=5+16; //"5" is axis C; "16" is axis inversion.
command=112+0; //Motor output #0
message=PLCCMD SET CNC VAR;
 timer=2;do{timer--;}while(timer>0);
 command=112+1; //Motor output #1
 parameter=1+16; //"1" is axis Y; "16" is axis inversion.
message=PLCCMD SET CNC VAR;
 timer=2;do{timer--;}while(timer>0);
exit(99);
};
```

3) Need to change PLC procedure that looks after sensors to store Y position instead of X. Change procedure name to M145.plc

M145.plc

```
#include pins.h
// Look after INPUT_GANTRY_S1 & INPUT_GANTRY_S2 input pins
// Position Y is stored in register #801 when sensor s1 triggered
// Position Y is stored in register #802 when sensor s2 triggered
// If both sensors triggered, then
// - Motion stopped
// - Position difference is calculated and stored into register #800
main()
{
    timer=0;
    message=PLCCMD_MOTION_CONTINUE;
    texit=timer+30;do{timer++;}while(timer<texit);
    mode_12=0;</pre>
```

```
ready=0;
s1 old=portget(INPUT_GANTRY_S1);
s2 old=portget(INPUT GANTRY S2);
do
 {
timer++;
s1=portget(INPUT GANTRY S1);
s2=portget(INPUT GANTRY S2);
model=mode 12\&1;
if (model==0)//if sensor 1 wasn't triggered
 {
 if (s1!=s1 old) //if triggered now
  {
     mode 12=mode 12|1; //set flag for sensor1
     position1=gvarget(5021+1); //Save the Machine Y position
  };
};
mode2=mode 12\&2;
if (mode2==0)//if sensor 2 wasn't triggered
{
 if (s2!=s2 old) //if triggered now
  {
     mode 12=mode 12|2; //set flag for sensor2
     position2=gvarget(5021+1); //Save the Machine Y position
  };
};
}while(mode 12!=3);
message=PLCCMD_MOTION_SKIP;
timer=2;do{timer--;}while(timer>0);
gvarset(801, position1); //send the position to myCNC software Register
#801
timer=50;do{timer--;}while(timer>0);
gvarset(802, position2); //send the position to myCNC software Register
#802
timer=50;do{timer--;}while(timer>0);
offset=position1-position2;
gvarset(800, offset);
timer=50;do{timer--;}while(timer>0);
```

```
exit(99);
};
```

4) Fix disable motor PLC procedure. Change procedure name to M211 (instead of M210)

M211.plc

```
#include vars.h
main()
{
connect=eparam;
message=PLCCMD_SET_CNC_VAR;
if (connect==0)
 {
  parameter=15; //OFF
}else
 {
  parameter=1+16; //"1" is axis Y; "16" is axis inversion.
 };
 command=112+1; //Motor output #1
 timer=2;do{timer--;}while(timer>0);
exit(99);
};
```

5) change the alignment macro to use Y axis instead of X axis

M139

```
M145
                      (# Set watching for GANTRY Sensors)
G91 G0 Y-1000 F500
                     (# Move toward Gantry Sensors)
( There is message delivery time from PLC to CNC control software)
( Need to wait some time till registers #800-802 will be updated )
( Add 0.5 seconds pause to get all the registers refreshed )
G4 P0.5
                    (# Pause)
G10 L81 P810 Q800
                   (# Get offset in pulses)
G10 L192 P810 Q5531 (# Calculate offset in units/mm)
G10 L190 P810 Q805 (# Add adjustment offset)
M211 P0
                     (# OFF the second motor, the Only first motor is
ON )
```

G10 L190 P810 Q5021	(# Add current machine position)
G28.9 Y810	(# Move 1 motor to adjust)
M210 P1 together)	(# ON the second motor, both motors are moved

From: http://docs.pv-automation.com/ - myCNC Online Documentation

Permanent link: http://docs.pv-automation.com/mycnc/gantry_alignment_macro_wizard?rev=1535294710

Last update: 2018/08/26 10:45

