


CNC Vision Setup


This manual is designed to introduce the reader to the setup process of the CNC vision system, and some of its applications.

Please note that the Vision System license for correcting the generated G-code using visual markers is a separate license that must be purchased in addition to the myCNC controller in order to be enabled (available as part of the [CNC Vision Kit package](#) in our [Online Shop](#)).


A video with the recap of the manual below is available here:



In order to set up the camera, you must go into the **CNC Settings > Config > Camera**. The screen presented to you will be the one shown below:



- **Camera Interface** allows to choose No Camera and a camera that is connected through LAN. If the camera is connected through LAN, the **Initialization line** must list the correct IP address of the camera.
- **IP Camera Initialization line** lists the camera IP for the connection to be established.
- **Pattern size** can be set experimentally to be about 30-50% larger than the marker itself, in order to account for the visual transition between the marker and its surroundings.
 - In the case of the particular marker used in this scenario, its size has been set to 160 pixels, which is on the low end of the relative pattern size - a larger pattern size is typically a safer choice in low-light conditions.
 - NOTE: The camera focus must be properly adjusted in order for the camera to recognize markers.




- **Region of interest** (in pixels) signifies the area in which the camera is actively looking for markers, and should usually be set to be equal or slightly smaller than the actual resolution of the camera. It is set automatically in the newer software versions during the calibration process (software versions after July 2019).
- **Pixel to length coefficient** is used to convert the pixels travelled into the actual physical distance moved, in mm. You are able to calibrate this for both the x- and the y-axes. In order to set up the correct coefficient for your camera, use the Calibrate button in the Camera tab, or consult the full set of manual set up instructions below (useful for older software versions).
- **Camera Shift** describes the distance the machine will move by if it does not locate a marker after it has been instructed to look for one. This can happen when the marker is not fully within the region of interest. In that case, the camera will keep on moving around until it either finds the marker or reaches the end of this specified Camera Shift. It is set automatically in the newer software versions during the calibration process. If no marker is found during the Camera Shift

process, the machine will be stopped.

- **Tool number** is typically assigned to be 10.
- **Camera offset** values are used to specify the distance from the camera to the working tool in the xy-plane.
- **Camera tool length** value is used to specify the distance from the camera to the working tool tip in the z-axis.
- **Ignore decoder errors** flag is set to OFF by default.
- **Shift Speed** describes the speed with which the machine is moving during its camera shift phase while trying to find the marker. NOTE: Deprecated on the newer versions of myCNC software.
- **Pattern Match Level** describes the level of parity with the original reference marker that each new marker must have for the system to recognize it. Higher numbers mean less parity (more differences between the markers), so as to avoid false positives it is advised to keep the numbers on the lower end of the scale. The graph below the Pattern Match Level indicates the parity levels during the machine search for markers, with the low points of the graph being indicative of the places where marker parity is highest (differences between new marker and reference are lowest).
 - If the program has issues locating markers due to those markers being slightly different (due to material imperfections, light reflections, etc), it is recommended to raise the Pattern Match Level until the program accepts the variations. However, raising this value too high will lead to false positives on marker recognition.
- **Image sensor correction** corrects for sensors with different aspect ratios. Use this if the marker image appears distorted or stretched when viewed through the Camera tab in myCNC software.

CNC Vision codes

The Vision system is controlled through a series of M-code PLCs which can be found in Settings > Config > PLC > Hardware PLC.



The following PLC procedures are used:

- M397 - start camera operations. [Show M397 code](#)

```
#include common.const.h

main()
{
    message=PLCCMD_CAMERA_START;
    textit=timer+10;do{timer++;}while(timer<textit); //pause to push the
    message

    exit(99);    //normal exit
};
```

- M399 - record the image, detect the marker position and store it in a dots array. [Show M399 code](#)

```
#define callback_address    var01
#define camera_count        var02
#define wait_camera         var03

main()
{
    camera_count=0;
    wait_camera=1;
    callback_address=3;
```

```

//delay after motion stopped
timer=300; do{timer--;}while (timer>0);

message=PLCCMD_WAIT_FOR_CAMERA;
timer=2;do{timer--;}while(timer>0); //pause to push the message

do
{
    if (wait_camera>1)
    {

        timer=100;do{timer--;}while(timer>0); //wait till motion started
        do { code=gvarget(6060); }while(code!=0x4d); //wait till motion
finished
        timer=300;do{timer--;}while(timer>0); //pause to push the message

        camera_count=wait_camera;
        wait_camera=1;
        message=PLCCMD_WAIT_FOR_CAMERA;
        timer=2;do{timer--;}while(timer>0); //pause to push the message

    };

}while (wait_camera>0);

exit(99); //normal exit
};

```

- M398 - calculate rotation, offset and distortion values and make a correction accordingly for the rest of the G-code file, then run the corrected G-code. [Show M398 code](#)

```

#include src/common.const.h
main()
{
message=PLCCMD_CAMERA_FINISH;
texit=timer+10;do{timer++;}while(timer<texit); //pause to push the
message

message=PLCCMD_MOTION_BREAK;
texit=timer+10;do{timer++;}while(timer<texit); //pause to push the
message

exit(99); //normal exit
};


```

These PLCs are added automatically into the G-code when importing a DXF file into myCNC. In order for the system to recognize the markers, the markers need to be drawn as roughly 6mm circles inside a separate layer named Camera within the DXF file. The user must have a valid Vision System license


to use this function.

Calibrating the CNC Vision System


- Go to the Camera tab of myCNC software by opening the Settings panel from the main screen
- Select an appropriate marker (pattern) size and click the Record button



- Click Calibrate. The software will automatically move a set distance in both the x- and the y-axes to determine the pixel to length coefficients.



The calibration process should be complete after the camera has moved in both the positive and the negative directions in both axes, and the results should be registered in Settings > Config > Camera:



Setting up the pixel to length coefficients


Obsolete method only used on program versions older than July 2019. In all recent versions the pixel to length coefficients is calculated automatically by the program during the calibration process.


[Click to expand the instructions](#)

The pixel to length coefficient is necessary for the camera to know how many millimeters it had moved after having traversed a certain number of pixel to the left/right/top/bottom of its original position. This procedure is done by finding the ratio of millimeters moved to pixels travelled. While it is automated in the newer versions of myCNC software, it can also be done manually in the older software versions.


In order to do so:

- 1. Go to the **Camera** tab of the myCNC software







2. Move your camera to the center of the marker and press the **Center** button



3. Press the **Start** and **Measure** buttons, and note the xy-position of the camera before moving it.



4. Move the camera some distance (in mm) and record that distance. Note the change from the original pixel xy-position, and find out how many pixels the camera has travelled over this movement. Divide the millimeters moved by the pixels travelled to obtain the pixel to length coefficient for each respective axis.




For example, in this setup, the machine has moved 12 mm to the right, while the x-position value has changed from 950 to 482.

$950 - 482 = 468 \text{ pixels}$
 $12 \text{ mm} \div 468 \text{ pixels} = 0.0256$

Therefore, the pixel to length coefficient is 0.256

5. Input the new coefficient into the **CNC Settings > Camera > Pixel to length coefficient** and press **Save**



6. Repeat the procedure for the other axis.

After both axes have been calibrated, the machine will now have a proper coefficient of the number of pixels it moved by versus actual distance travelled in millimeters.

Using the hotkeys to move the camera


In order to move the camera straight from the Camera tab, a set of hotkeys have been designed specifically for that purpose. Note that the hotkeys are only present in the more recent versions of myCNC software. Please update the myCNC application if the camera hotkeys are not present in your profile version.

HOTKEY	ACTION
Arrow Up	Move in the positive y-direction
Arrow Right	Move in the positive x-direction
Arrow Down	Move in the negative y-direction
Arrow Left	Move in the negative x-direction
Space	Switch the step jog size (00.1 through 1 mm)
Hold Control and Arrow keys	Move by the selected step jog


CNC Vision Example

The CNC Vision correction of a program to be used on a shifted or distorted working material can be done easily after the markers have been calibrated. In order to open and use a file with the CNC Vision system, use the following instructions:


1. From the myCNC software's main screen, click the Open DXF File button.




2. Select the particular DXF file you would like to open.
3. When selecting the tools, include Camera as one of the tools, and assign to it the same tool number as the one specified in the Camera Settings (this will be Tool 99 in our case). Assign the other tool or tools and their priorities as necessary for your particular program.



4. Once you have loaded the DXF file, the program should now have inserted the M397, M398, and M399 macros which refer to camera actions into the program G-code.



5. Press **Run**.



The machine will move the camera towards the supposed marker positions, and, if the markers are not immediately present in the Region of Interest, will move around this supposed marker position by the distance specified by the Camera Shift. After running through the camera macros and locating all of the markers for which the program has been calibrated, the program will automatically adjust for any shift or distortion that was introduced, and will immediately begin running the main program.

NOTE: The program will not begin the main cutting process unless all the markers that were expected to be adjusted for have been located.

Camera troubleshooting

A camera troubleshooting guide is available here: [Camera Troubleshooting](#)

From:
<http://docs.pv-automation.com/> - myCNC Online Documentation

Permanent link:
<http://docs.pv-automation.com/quickstart/mycnc-quick-start/cnc-vision-setup?rev=1579201669>

Last update: 2020/01/16 14:07

