Start/Stop Setup

Additional information on Program Stop and the associated PLC procedures is available here: Stop/End program button commands.

This article is designed to introduce the reader to the basic setup process of the Start/Stop procedure in myCNC settings.

Upon opening **CNC Settings > Preferences > Start/Stop**, the following screen is presented to the user:

SYS PLC Info	Support Camera Cutchart Config	SAVE
CNC Settings	Cutting ON commands	M20; M71; M03;
Axes/Motors Inputs/Outputs/Sensors	Cutting OFF commands	M21: M74: M05:
Network	cutting of r commands	M21, M74, M03,
Motion	Soft stop time,s	0.05
▶ PLC	Limit stop time,s	0.05
G-codes settings		Deceleration time_if "Stop" pressed
Macro List		
▶ Macro Wizard	After Stop Handler	Not defined
Probing Wizard	On Start	
Common	Charle Caffel Inclusion for the full teacher the	
Start/Stop	Check Soft Limits for the full toolpath	M
Shape Library Settings	Toolpath Position checking, axes	🕱 x 🐹 y 🕱 z 🐹 a 🕱 b 🕱 c 🐹 u 🕱 v
Screen		Current position & Toolpath position should be equal in given
Parking Coordinates		axes
▶ Technology	Goto Toolpath Position for axes	🗙 x 🔀 y 🕱 z 🔀 a 🕱 b 🕱 c 🕱 u 🕱 v
Camera		Cutting/Snindle ON & tool moves to toolngth
5 axes RTCP Ranel/Rendant		position on Start for given axes
 Hardware 		Direct Move V
▶ Advanced		
	Lift Height	10
	Move-to-Toolpath speed	6000
	Current position as Start ((*)Disabled by default)	×
	Reset work Position on "Reset-NC", "Tie" pressed.	×



On Start behaviour

A common scenario with mill and plasma machines is having to move the plasma torch or any other working tool away from the cutting point in the middle of running a program, for cleaning/inspection/etc. In order to continue the cutting process smoothly after having stopped the machine and moved the working tool, the **On Start** section of the Start/Stop menu can be used to properly describe the behaviour of the machine when it is started again from the middle of the program.

The Check Soft Limits for the full toolpath toggle specifies whether the user wants to check the entire program for issues with soft limits (program work position going outside of soft limits) before starting the program. If the toggle is set to ON, and there are issues with the soft limits present, the program will not start. This setting is not recommended for extremely large programs, as it takes a lot of time to run the check. Programs under 10 000 lines of code are best suited for this process.

SYS PLC Info	Support Camera Cutchart Config	SAVE
CNC Settings Axes/Motors hputs/Outputs/Sensors Network Motion PLC G-codes settings DXF import settings Macro List Macro Wizard Profing Wizard Profing mizard	Cutting ON commands Cutting OFF commands Soft stop time,s Limit stop time,s After Stop Handler On Start	M20; M71; M03; M21; M74; M05; 0.05 0.05 Deceleration time, if "Stop" pressed Not defined
Common Start/Stop Shape Library Settings Screen Work Offsets Parking Coordinates Parking Coordinates Technology Camera 5 axes RTCP Panel/Pendant Hardware Advanced	Check Soft Limits for the full toolpath Toolpath Position checking, axes Goto Toolpath Position for axes Lift Height	Image: Second system Image: Second system
	Move-to-Toolpath speed Current position as Start ((*)Disabled by default) Reset work Position on "Reset-NC", "Tie" pressed.	6000 X

The behaviour of the machine with all the flags turned OFF is to simply continue cutting straight from the the point to which the working tool has been moved, as if it was still at its original position. This can lead to issues with cutting, since this effectively fails to cut the particular part at which the machine has been stopped. In order to correct this, two options are present.

- **OPTION 1:** Block the machine from starting up again if the new start point for the cut is not the same as the stop point.
- **OPTION 2:** After the machine has been stopped and move, automatically move it back to the original stop position before attempting to cut again.

NOTE: Only one option can be chosen for each given axis

Option 1: Block the machine from running

In order to block the machine from running if its new start position is different from its stop position, the user can select the particular axes for the machine to check before running. In the example below, the x- and y-axes have been selected to check their position before attempting to move again.

SYS PLC Info	Support Camera Cutchart Config	SAVE
CNC Settings Axes/Motors Inputs/Outputs/Sensors Network Motion PLC G-codes settings DXF import settings Macro List Macro Wizard Probing Wizard Proferences Common Start/Stop Shape Library Settings Screen Work Offsets Parking Coordinates Technology Camera 5 axes RTCP Panel/Pendant Hardware Advanced	Cutting ON commands Cutting OFF commands Soft stop time,s Limit stop time,s After Stop Handler On Start Check Soft Limits for the full toolpath Toolpath Position checking, axes Goto Toolpath Position for axes Lift Height Move-to-Toolpath speed Current position as Start ((*)Disabled by default) Reset work Position on "Reset-NC", "Tie" pressed.	M20; M71; M03; M21; M74; M05; 0.05 $\overline{0.05}$ Deceleration time, if "Stop" pressed Not defined \checkmark

This will check the axes and, if any position values for each selected axis are different after the move, will stop the program when the Run button is pressed, as seen in the image below:



Option 2: Move back to stop position

The second option allows the operator to stop the machine, move the working tool to a desired position and then, after pressing the Run button, makes the machine automatically return to the original stopping position and resumes the cut from there. This is especially useful on large machines, where the operator may stop the machine in the middle of running the program to check the working tool and then has to move it closer in order to inspect it.

In order to set this option up, the user needs to select the particular axes for which the machine will check its position values and, if any of them are different from their position values at the stop point, the machine will move the working tool back in place. In the example below, axes x, y and z have been selected to go back to the original stopping point, therefor allowing the user to lift the tool and move it closer towards themselves, then pressing Run for the tool to move back:

SYS PLC Info	Support Camera Cutchart Config	SAVE
CNC Settings Axes/Motors Inputs/Outputs/Sensors Network Motion PLC G-codes settings DXF import settings Macro List Macro Wizard Preferences Common Start/Stop Shape Library Settings Shape Library Settings Shape Library Settings Shape Library Settings Start/Stop Shape Library Settings Start/Stop Shape Library Settings Start/Stop Shape Library Settings Start/Stop Shape Library Settings Start/Stop Shape Library Settings Start/Stop Shape Library Settings Average Start Start/Stop Start/Stop Shape Library Settings Average Start Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop Start/Stop S	Cutting ON commands Cutting OFF commands Soft stop time,s Limit stop time,s Limit stop time,s After Stop Handler On Start Check Soft Limits for the full toolpath Toolpath Position checking, axes Goto Toolpath Position for axes Lift Height Move-to-Toolpath speed Current position as Start ((*)Disabled by default) Reset work Position on "Reset-NC", "Tie" pressed.	M20; M71; M03; M21; M74; M05; 0.05 0.05 Deceleration time, If "Stop" pressed Not defined \checkmark
	Reset work Position on Reset-NC, The pressed.	2

The Lift Height has been set to be 15 mm, allowing the machine to lift the working tool before moving as to prevent any collision with the working part. Note that this value will be different depending on the specific part and machine configuration.

These two options can be set to be different for different axes - for example, the x- and y-axes can be set to return back to the original stopping point, while the z-axis can be set to block movement if the working tool has been moved up or down, as in the image below. Note however, that only one option is available for each specific axis.

• (11:48:17) myCNC control software. Ver	r:1.88.3064- [lib-shape-045.nc]	88
SYS PLC Info	Support Camera Cutchart Config	SAVE
CNC Settings Axes/Motors > Inputs/Outputs/Sensors Network Motion > PLC G-codes settings DXF import settings Macro List > Macro Wizard > Probine Wizard	Cutting ON commands Cutting OFF commands Soft stop time,s Limit stop time,s After Stop Handler	M20; M71; M03; M21; M74; M05; 0.05 Deceleration time, If "Stop" pressed Not defined
Preferences Common Start/Stop Shape Library Settings Screen Work Offsets Parking Coordinates	On Start Check Soft Limits for the full toolpath Toolpath Position checking, axes	✓ x x y y z x a x b x c x u x v Current position & Toolpath position should be equal in given axes
 Technology Camera Saxes RTCP Panel/Pendant Hardware Advanced 	Goto Toolpath Position for axes Lift Height Move-to-Toolpath speed Current position as Start ((*)Disabled by default)	Image: Second state of the second s
	Reset work Position on "Reset-NC", "Tie" pressed.	×

Additional Notes

Start/stop can be performed via the 0xffffff (Stop) and 0xfffffe (Start) commands. For instance,

gvarset(0xffffff,1); //Stop Program

This can be used in procedures such as the HOMING_HANDLER Software PLC.

Additionally, the following global variables can be used:

GVAR_EXT_REFRESH_NC	100001	refresh nc program
GVAR_EXT_PLAYER_PLAY	100002	play
GVAR_EXT_RESET_NC	100003	reset nc program

Pause

As of December 2022, the myCNC firmware features the Pause functionality. This allows to:

- Adjust the Overspeed % to 0 (complete stop)
- Use the Pause button action="player-pause" for pause/start

As opposed to the **Stop** button, which stop the program followed by the ability to start from the stop point, **Pause** is a smooth decrease in speed to zero without stopping the program execution. Essentially, the **Pause** brings the base frequency to a halt. When the frequency is brought back up, the process continues. This makes the **Pause** resemble a "sleep" mode. From: http://docs.pv-automation.com/ - myCNC Online Documentation

Permanent link: http://docs.pv-automation.com/quickstart/mycnc-quick-start/start-stop-setup



Last update: 2022/11/30 16:20