## SheetCam Tips


## Path rules

SheetCam allows the user to set a combination of path rules. In the example below, the path rules result in a decrease in speed on given sections of the workpath.

SheetCam screenshot:

	Path rules				×		
	Rule set my-rules	~	Rename	Delete	Load	Save	
S1	<ul> <li>✓ On outside corners tighter than 45 degrees set feed to 50 % 5</li> <li>✓ On circles smaller than 50 mm set feed to 60 %</li> <li>✓ On arcs smaller than 50 mm set feed to 40 % 5 mm before the</li> </ul>			mer.			
	Always apply rule set	Show rule names in g-code	e	~			
+	CK +	Cancel	Help				
,p.,		<u> </u> J					

## Result in myCNC:



As can be noted from the Path Rules, the example above will have a speed reduction to 40% of the original speed at the arcs on each of the part's corners.

From: http://docs.pv-automation.com/ - myCNC Online Documentation

Permanent link: http://docs.pv-automation.com/other/sheetcam

Last update: 2022/02/14 12:24

